



REV.	DATE	DESCRIPTION
3	3/00	ECN# 072/00
4	7/06	ECN# 054/06
5	9/11	ECN# 02A/11

# NOTES:

SET THERMOSTAT ON HIGH FOR TESTING.  
 MARK PART NO. ON BACK WITH A BLACK MARKER.

#2 ATTACH BLACK WIRE TO THE MALE SILVER TERMINAL.

USE #6 BLUNT SCREWS ON FUSE HOLDERS  
 USE 10-24 SCREW AND NUT ON CONTROL AND GROUND LUG.



LOCATION




CANARM

TOLERANCE: +/- .031 UNLESS OTHERWISE SPECIFIED

DRAWN BY: A.CHING

CHKD BY:

SCALE: NONE

DATE: 03/27/00

DESCRIPTION: HLW-93 WIRING BOX ASSEMBLY

MATERIAL: -

DIMENSIONS -

DWG.NO.: **G4952**